## MR-1 CHECK OFF LIST FOR NON-CATEGORICAL COMPANIES

## **CRAFT TEXTILE**

## 27220136-outlets 1 & 2

1.	MONTH OF MARCH 1, 2009 THRU MARCH 31, 2009		
2.	Is Outlet # (8 digit) Correct?	N	N/A
3.	Is average Total flow-gal.day stated in space provided?	N	N/A
4.	Is max. Total flow-gal day stated in space provided? Y	N	N/A
5.	Is method used to calculate water stated?	N	N/A
6.	Are number of working days stated?	N	N/A
7.	Are there any parameters which have exceeded PVSC Local Limits?  Y		N/A
8.	Is proper compliance/non-compliance statement provided?	N	N/A
9.	Have correct number of samples been submitted?	$\mathbf{N}$	N/A
10.	Has PHC result been listed on MR-1 report?	N	N/A
11.	Has sample number been reported in space provided?	N	N/A
12.	Have all regulated parameters been listed on MR-1?	N	N/A
13.	Has sample type been stated on MR-1?	N	N/A
14.	Have all samples been taken during this reporting period?	N	N/A
15.	Has NJDEPE certified lab/hogen/ased?	N	N/A
16.	Have analytical results been submitted on copies of Laboratory stationery?	N	N/A
17.	Have results been written in space designated on MR-1?	N	N/A
18.	Is correct method used to preserve samples stated on MR-1?	N	N/A
19.	Has MR-1 been signed by authorized representative?	N	N/A
20.	Has information been submitted on proper MR-1 form?	N	N/A
21.	Remove Arsenic from report if sampling not required Y	N	N/A
			THE REAL PROPERTY AND PROPERTY

# MR-1 CHECK OFF LIST FOR NON-CATEGORICAL COMPANIES

Craft Textile		. 21	7220136			
First Reviewer: co	omments on	deficiencies 2	OMPLETE :			
				•		· .
Date Reviewed	5/13/09	Date sent to user				· ———
Date due back		Reviewe	r <i>c.</i> y.m.	· . · · · · · · · · · · · · · · · · · ·	ngga saku	·
Second review co	mments on	deficiencies				
						· · · · · · · · · · · · · · · · · · ·
Date Reviewed		Date s	ent to user			
Date due back		Review	er	· · · · · · · · · · · · · · · · · · ·		
Date		Reviewer		 		

2 2009

#### PRETREATMENT MONITORING REPORT

NAME:

Craft Textile Printing Co., Inc.

MAILING ADDRESS:

P.O. Box 2761, Paterson, NJ 07509-2761

**FACILITY LOCATION:** 

44 Beech Street, Paterson, NJ 07501

Category & Subpart: 9999

OUTLET # 1

Contact Official: H.R. Casparian

Telephone # 973-278-3818 INDUSTRIAL DEPARTMENT

New Customer ID/Outlet ID: 27220136-1

Old Outlet Designation: 27400061

Average Maximum

APR

Regulated Flow(gal/day) Total Flow (gal/day)

27493

30242

**END** START 3/1/2009 3/31/2009 m/d/yr m/d/yr

**MONITORING PERIOD** 

Method Used:

Gallons in less 5% evap. divided by

production days in month (10)

Production Rate:

N/A

<u>Parameter</u>		Mas	s or Concentra	<u>ation</u>	# of Samples	Sample Type
and the same of th		Mon Avg	<u>Maximum</u>	<u>Units</u>	4.0	Comp/Grab
Zinc	Sample Measurement	0.0237	Same Special	mg/l	1	Comp
	Permit Requirement	1.67	1	mg/l		- T
Copper	Sample Measurement	0.0128		mg/l	1	Comp
	Permit Requirement	.092/3.02		mg/l		
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement				1	Till by and
	Permit Requirement				1.63	1516
	Sample Measurement				197 3	100
	Permit Requirement				1110	1
	Sample Measurement				14	1,
	Permit Requirement					20 -
	Sample Measurement			ρ.	more thank	1000
	Permit Requirement				E 18 " " "	17.00
	Sample Measurement	13000	10970		169	1997
	Permit Requirement		4 3		1000	19
	Sample Measurement		150			197103
-	Permit Requirement	11	(5)			
	Sample Measurement	1 /10/	42			
	Permit Requirement		0 0			
	Sample Measurement	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	100			
	Permit Requirement	Ve	Lept.	3		
	Sample Measurement	1507	167		И	
	Permit Requirement	77359	21200			

PVSC Form MR-1 Rev: 4 6/87 P1

Certification of Non-Use if applicable (use additional sheets)

Compliance or non-compliance statement with compliance schedule for every parameter used:

< Local Limits:

ZN, CU

> Local Limits:

N/A

< Threshold Values

ZN, CU

> Threshold Values:

N/A

Craft Textile Printing Co., Inc., is in compliance with local limits.

Explain "Method for preserving samples:

Refrigerator until end of pumping, then nitric acid as a preservative to a pH less than 2.

I certify under penalty of law that this document and attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or the persons directly responsible for gathering the information, the information submitted is. to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

403.6(a)(2)(ii) revised by 53 FR 40610. October 17, 1988

Signature of Principal

executive or authorized agent

H.R. Casparian-President Name-Title 3/31/2009 Date

PVSC Form MR-1 Rev: 5 3/91 P2

#### PRETREATMENT MONITORING REPORT

NAME:

Craft Textile Printing Co., Inc.

MAILING ADDRESS: FACILITY LOCATION: P.O. Box 2761, Paterson, NJ 07509-2761 44 Beech Street, Paterson, NJ 07501

Category & Subpart: 9999

OUTLET #2

Contact Official: H.R. Casparian

Telephone # 973-278-3818

New Customer ID/Outlet ID: 27220136-2

Old Outlet Designation: 27400062

MONITORING PERIOD

START

3/1/2009

m/d/yr

**END** 3/31/2009 m/d/yr

Average Maximum Regulated Flow(gal/day)

N/A

Total Flow (gal/day)

14958

16454

Method Used:

Gallons in less 5% evap. divided by

production days in month (10)

Production Rate:

N/A

<u>Parameter</u>		Mass or Cond	<u>centration</u>	# of Samples	Sample Type
		Mon Avg Maximu	um Units		Comp/Grab
Zinc	Sample Measurement	0.0245	mg/l	1	Comp
	Permit Requirement	1.67	mg/l		3.
Copper	Sample Measurement	0.0161	mg/l	1	Comp
1000	Permit Requirement	.092/3.02	mg/l		
	Sample Measurement				
	Permit Requirement				
	Sample Measurement				
	Permit Requirement				E GIOTA
	Sample Measurement			18.8	
	Permit Requirement			TX.	
	Sample Measurement			(0 10	V
	Permit Requirement				Mar
	Sample Measurement			1	2 2
	Permit Requirement			100	10,000
	Sample Measurement			153	
	Permit Requirement			150	90%
	Sample Measurement			1/3	-
	Permit Requirement				E SE VE E
	Sample Measurement				
	Permit Requirement				
	Sample Measurement		1		
	Permit Requirement			AFE	
	Sample Measurement			12:3000	1000
	Permit Requirement			(1)	£ -\
	Sample Measurement			11	100
	Permit Requirement		1 /0	5 1	7
	Sample Measurement		000	IAP!	
	Permit Requirement		(6	151	13
	Sample Measurement		1/1	Industrial	1
	Permit Requirement			outal D	ep V

PVSC Form MR-1 Rev: 4 6/87 P1

\* COPPER SAMPLE ON MR-3 \*

Certification of Non-Use if applicable (use additional sheets) N/A

Compliance or non-compliance statement with compliance schedule for every parameter used:

ZN, CU < Local Limits:

> Local Limits:

N/A

ZN, CU < Threshold Values

> Threshold Values:

N/A

Craft Textile Printing Co., Inc., is in compliance with local limits.

Explain "Method for preserving samples:

Refrigerator until end of pumping, then nitric acid as a preservative to a pH less than 2.

I certify under penalty of law that this document and attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or the persons directly responsible for gathering the information, the information submitted is. to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

403.6(a)(2)(ii) revised by 53 FR 40610, October 17, 1988

Signature of Principal

executive or authorized agent

H.R. Casparian-President Name-Title 3/31/2009 Date

PVSC Form MR-1 Rev: 5 3/91 P2



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908-789-8900 Fax: 908-789-8922

## **Report of Analysis**

Client:

**Craft Textile Printing** 

Project:

**Permit Renewal** 

Client Sample ID: OUTLET-1

Lab Sample ID:

A1713-01

**Date Collected:** 

3/5/2009

Date Received:

3/5/2009

SDG No.:

A1713

Matrix:

WATER

% Solids: 0.00

CAS No.	Analyte	Conc.	Qualifier	Units	DL	Dilution	Date Prep	Date Anal.	Method
7440-43-9	Cadmium	0.400	U	ug/L	0.400	1	3/6/2009	3/6/2009	EPA 200.7 ICP 4
7440-50-8	Copper	12.8		ug/L	2.600	1	3/6/2009	3/6/2009	EPA 200.7 ICP 4
7439-92-1	Lead	6.650		ug/L	1.800	1	3/6/2009	3/6/2009	EPA 200.7 ICP 4
7439-97-6	Mercury	0.0700	U	ug/L	0.0700	1	3/9/2009	3/10/2009	EPA SW-846 245.1
7440-02-0	Nickel	3.700	U	ug/L	3.700	1	3/6/2009	3/6/2009	EPA 200.7 ICP 4
7440-66-6	Zinc	23.7		ug/L	5.600	1	3/6/2009	3/6/2009	EPA 200.7 ICP 4

Comments:

U = Not Detected

DL = Method Detection Limit or Instrument Detection Limit

J = Estimated Value

B = Analyte Found In Associated Method Blank

N = Spiked sample recovery not within control limits 6



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908-789-8900 Fax: 908-789-8922

### **Report of Analysis**

Client:

**Craft Textile Printing** 

**Date Collected:** 

3/5/2009

Project:

Permit Renewal

Date Received:

3/5/2009

Client Sample ID: OUTLET-2

SDG No.:

A1713

Lab Sample ID:

OUIDEI.

Matrix:

WATER

A1713-02

% Solids:

0.00

CAS No.	Analyte	Conc.	Qualifier	Units	DL	Dilution	Date Prep	Date Anal.	Method
7440-43-9	Cadmium	0.400	U	ug/L	0.400	1	3/6/2009	3/6/2009	EPA 200.7 ICP 4
7440-50-8	Copper	16.1		ug/L	2.600	1	3/6/2009	3/6/2009	EPA 200.7 ICP 4
7439-92-1	Lead	1.800	U	ug/L	1.800	1	3/6/2009	3/6/2009	EPA 200.7 ICP 4
7439-97-6	Mercury	0.0700	U	ug/L	0.0700	1	3/9/2009	3/10/2009	EPA SW-846 245.1
7440-02-0	Nickel	3.700	U	ug/L	3.700	1	3/6/2009	3/6/2009	EPA 200.7 ICP 4
7440-66-6	Zinc	24.5		ug/L	5.600	1	3/6/2009	3/6/2009	EPA 200.7 ICP 4
Comments:	•.			_					

U = Not Detected

DL = Method Detection Limit or Instrument Detection Limit

J = Estimated Value

B = Analyte Found In Associated Method Blank

N = Spiked sample recovery not within control limits 7

D	En	NTE	Ð	1
HAIN	OF CU	STODY	RECO	ORD

### 284 Sheffield Street, Mountainside, NJ 07092 (908) 789-8900 Fax (908) 789-8922 www.chemtech.net

CHEMTECH PROJECT NO.

QUOTE NO. A 1 1 1 3

COC Number 0 7 8 4 9 9

	CLIENT INFORMATION			7	CLIENT PF	OJECT IN	FORMA	TION			•			CLIENT	BILLIN	(G INFO	RMATION	
COMPANY:	PROJECT NAME:								BILL TO: PO#:									
ADDRESS: P	CRAFT TEXTUR PRINTING CO., IN	PROJEC				LOCAT	TION:				ADDRE	ss.						
PA C	TECSON STATE NJZIP 2761	PROJEC			ED.	20.071					CITY:					STAT	E: ZIP:	
	H. R. CASPAGAN	e-mail:	I. Wira	VA C	<u>en.</u>						ATTEN	TION		<u> </u>		PHON		
ATTENTION:		e-man.						·			ATTEN	HON:		1317	ANA	LYSIS	NE;	
	-278-3818 FAX: 973-523-8677	PHONE:		ATA	DELIVE	FARABLE IN		ATION				\S	1	0/		$\overline{}$	77	//
FAX;	DAYS .	☐ RESU			<del></del>	USEPA CL				7	15%	THE STATE OF THE S	JOH	r /			///	
	DAYS ·	C) RESU	ILTS +	QC		New York	State A			X		180					///	
EDD:	/ED TAT: D YES D NO	☐ New .				New York : Other		SP 'A'	305			54/	//	//	//	//		
	TURNAROUND TIME IS 10 BUSINESS DAYS	□ EDD	•					<u> </u>	/2	MALTA	224	5	6	/7	/8	/ 9		451550
CHEMTECH			SAM			APLE ECTION	LES				PHES	ERVA	IIVES	_				AENTS Preservatives
SAMPLE	PROJECT SAMPLE IDENTIFICATION	SAMPLE MATRIX	TYF S		DATE	TIME	# OF BOTTLES								<u> </u>		A-HCI C-H-SO	B-HNO <sub>3</sub> D-NaOH F-Other
115		<u> </u>	COMP	GRAB		l		1	2	3	4	- 5	6	7	8	9	E-ICE	F ~Other
1.	OUTLET #1	<u> </u>	X		7 7 7	113000	2	X		<u> </u>				ļ		ļ	. "	
2.	Owner #2	<b>]</b>	X		35/09	113-0m	7	$\perp$ X	<u> </u>	X				-	ļ	ļ		
3.		<u> </u>				ļ				L				ļ	ļ	ļ	137	
4.							<u> </u>	L		ļ		<u> </u>		<b> </b>	ļ	<u> </u>		
5.						L	ļ			ļ		<u> </u>		ļ	<u> </u>	<b> </b>	-	
6.		<u> </u>								<u> </u>					<u> </u>			
7.		<u> </u>					<u> </u>					<u> </u>			<u> </u>			
8.											<u> </u>		ļ	<u> </u>	ļ	L		
9.																		
10.										<u> </u>				<u> </u>	<u> </u>	<u> </u>		
	SAMPLE CUSTODY MUST BE DO	CUMENTE	D BEI	OW														400
RECNOUISHED BY	SA 101 11 AM 1	Con	۲.	٠	MeQ	tions of bot H. extracti					Comp jar for			Non Co	mpliant		ooler Temp e in Cooler?:	ves
RELINQUISHED BY	DATE/TIME: RECEIVED BY:				Com	ments:	•. •	•								101	- III COOIGI ;;	753
2. RELINOUISHED BY	DATE/TIME: /2. RECEIVED FOR LA	UB BY: /	1						e.	HIPPEN	VIA: CI	IENT:	T HAN	יו ואַם מו	/ERED	Clove	RNIGHT Ships	nent Complete:
3.	DATE/TIME: 12:55 RECEIVED FOR LA	2/	11811	7 A	Page	<u> </u>	of_	<u> </u>		HEFED					UP [			es □no2
	1 /					NT VE		011514	TCOLL	0001	DIAM		401.00	CORV				